## TRANSMISSION CORPORATION OF ANDHRA PRADESH LIMITED

From

Chief Engineer Transmission Vidyut Soudha Hyderabad – 82. M/s. Asbesco (I) Pvt. Ltd.,

M/s. Asbesco (I) Pvt. Ltc 1-A,KBR Complex 4,Ho-Chi-Minh Sarani Calcutta - 700 071.

Lr.No.CPT 832/APT 728/HW for MOOSE/Asbesco/D.NO. 56 /dt. 16 872/

Sirs,

Sub: APT 7 and 8/98 - Supply of Hardware and Accessories suitable for Moose

ACSR - Performance Certificate issued - Reg.

Ref: Your Lr.No.ACF'Q-3(Part-V)/0235/BN/dt.12.7.2000.

\*\*\*\*

As requested by you in your letter, cited in the above reference, the "Performance certificate" for supply of Hardware and Accessores suitable for Moose against the Specn.Nos.APT 7&8/98 in enclosed herewith. The receipt of the same may be acknowledged.

Yours faithfully

Chief Engineer

Transmission

Encl: 1 No.

asbesco-lr.doc

## TRANSMISSION CORPORATION OF ANDHRA PRADESH LIMITED

O/o.Chief Engineer/Transmission Vidyut Soudha/Hyderabad-82

## PERFORMANCE CERTIFICATE (To whome so ever it may concern)

M/s. Asbesco (India) Pvt. Ltd., 1-A, KBR Complex, 4, Ho-Chi-Minh Sarani, Calcutta - 700071 have executed the following orders within the delivery schedule.

SI No.	Order No.& Date	Item	Qty.
	· 		
1.	CPT 21/APT7/98	Single Tension	500 Nos
	RM-2581	Hardware for	
	Dt.14.9.98	Moose.	
		Single Susp.	1000 Nos.
		Hardware for	
	$\psi_{i}(x) = \psi_{i}(x)$	Moose.	
		Single Susp.	100 Nos.
		Hardware for	
		Moose.(with AAH)	
		Double Tension	100 Nos.
	•	Hardware for	
		Moose.	
2.	CPT21/APT8/98/	Mid span comp	1000 Nos.
	RM-1971	joints for Moose.	
	Dt.23.9.98.		

No adverse reports are received from the field so far.

CHIEF ENGINER
TRANSMISSION

asbesco-lr.doc