

No. G2010091E

Electric Power Industry Quality Inspection & Test Center  
of Electric Power Equipment & Instruments

# INSPECTION AND TEST REPORT


(Power Insulator & Arrester Station) No. G2010091E

**Product:** ± 800 kV HVDC Repair Sleeve for ACSR Lapwing

**Manufacturer:** ASBESCO (india) PVT LTD., KOLKATA, INDIA

**Consignor:** ASBESCO (india) PVT LTD., KOLKATA, INDIA

**Test Type:** Client test

 त्वरप्रिड signature) designation) (Date)	<input checked="" type="checkbox"/>	I. Approve/Released for Fabrication/Construction.
	<input checked="" type="checkbox"/>	II. Approve/Released for Fabrication/Construction Subject to Incorporation of Comments. Modification as Noted. Revised Drawing Required.
	<input checked="" type="checkbox"/>	III. To Be Resubmitted for Approval after Incorporating the Comments.
	<input checked="" type="checkbox"/>	IV. For Information & Record.
	<input checked="" type="checkbox"/>	V. Not approved.
Sep 06, 2010		Power Grid Corporation of India Ltd. (Corporate Engg. TL) Surgeon.

**Quality Inspection and Test Center:**

Address: XiaoYingDongLu No.15, QingHe, Beijing, China  
Post Code: 100192  
Tel: +86- 010-62931468  
Fax: +86- 010-62913139